# Full Reserve Study Armstrong Community Development District Orange Park, Florida



Prepared for FY 2023 Report Date: May 1, 2023





May 1, 2023

Ms. Marilee Giles, District Manager Governmental Management Services 475 West Town Place, Suite 114 St. Augustine Florida 32092

Re: Reserve Study Report for Armstrong Community Development District

Dear Ms. Giles:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. A site visit was conducted to determine the condition of your major components and provide an opinion of their remaining useful life.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by CAI and the Standards of Practice establish by APRA. Once you have reviewed this report and considered recent expenditures and any historic cost data, we will make necessary adjustments

Respectively submitted,

CRShamand

Charles R. Sheppard RS PRA CCI

Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275

www.communityadvisors.comm









#### SPECIAL NOTICE

THIS RESERVE ANALYLSIS INCLUDED A VISUAL OBSERVATION OF MAJOR COMPONENTS FOR YOUR PROPERTY. NO DISTRUCTION TESTING OR OTHER TESTING WAS CONDUCTED TO DETERMINE COMPONENT CONDITION. OUR ANALYSIS INCLUDES COMPONENTS WITH REPLACEMENT COST AND USEFUL LIFE PROJECTIONS THAT ARE TYPICAL FOR THIS TYPE OF FACILITY.

THIS ANALYSIS IS NOT A SAFETY INSPECTION OR STRUCTURAL INSPECTION AND WE RECOMMEND THE ASSOCIATION CONDUCT THOSE INSPECTIONS ON A REGULAR BASIS WITH OTHER CONSULTANTS.

## TABLE OF CONTENTS

EXECUTIVE SUMMARY	
Executive Summary	1-1
Financial Summary - Recommended Funding Plan	1-2
Cash Flow Funding Plan VS Fully Funded	1-3
Current Funding Plan vs Recommended Funding Plan	1-4
CURRENT FUNDING PLAN - SECTION NOT USED	
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
Asset Current Cost by Category	4-5
COMPONENT INVENTORY	
Component Inventory	5-1
Component Detail Index	5-4
Component Detail	5-6
DISCLOSURERS & INFORMATION	
Report Navigation	6-1
Methodology & Information	6-2
Terms of Service	6-3
Definitions	6-1

# **Executive Summary**

#### **Account Information**

Account Name Armstrong Community Development District Account Number 1910

City Orange Park Last Site Visit April, 14 2023
State Florida Report Date May, 1 2023

In Service Date August, 1 2019 Report Version 2

Total Units 483 Fiscal Year Start October, 1 2023
Study Level 1 Reserve Study Fiscal year End September, 30 2024

#### **Reserve Fund Information**

Current Component Replacement Cost \$838,500

Number of Components 45

Reserve Fund Beginning Balance \$0

Billing Term Annually

### **Component Funding (Straight Line)**

Recommended First Year Reserve Fund Contribution
Interest Rate on Reserve Deposits
Inflation Rate on Replacement Cost

\$66,656

0%

### Pooled Cash (Current Funding Plan) THIS SECTION NOT USED

Current Year Reserve Fund Contribution Interest Rate on Reserve Deposits Inflation Rate on Replacement Cost Annual Contribution Increases

## **Pooled Cash (Recommended Funding Plan)**

Recommended First Year Reserve Fund Contribution
Interest Rate on Reserve Deposits
Inflation Rate on Replacement Cost
Annual Contribution Increases

\$53,288
4.0%
1.0%

#### Comments

- Date in service for components is the month of the Certificate of Occupancy. Streets are not included per District Manager.
- The District has not established reserves, therefore the current contribution section of the report is omitted.
- Recommended funding plan requires moderate contributions for adequate funding.

# **Armstrong Community Development District Financial Summary - Recommended Funding Plan**

Begining Balance: \$0 Fully Funded: \$214,524 Tax Rate:0%

	C	U		•	,					
	A SUN OF	_	Right Septiment of the	ior			di di di	· ×	28 CE 12 CE	30 ~ 1
	200° ×	a diga	AND SE CONTRO	s si si		, Kes	eige ariti	Asi Salate	यह द्वीती यह विद्वारी	in and
Year	€8,00°	Tallada de	And Solid	Ogst Acous	A ST	2° 40° 5°	No view	AS PARTY OF	र्रहेष्ठ रिक्का, रहे	so Charle
23-24	838,500	3.5%	53,288	0	4.00%			53,288	266,439	20%
24-25	867,848	3.5%	53,821	0	4.00%	4,284		111,393	321,725	35%
25-26	898,222	3.5%	54,359	0	4.00%	6,193	10,915	161,030	369,258	44%
26-27	929,660	3.5%	54,903	0	4.00%	8,274	9,091	215,115	422,007	51%
27-28	962,198	3.5%	55,452	0	4.00%	10,823		281,389	487,735	58%
28-29	995,875	3.5%	56,006	0	4.00%	13,496		350,891	557,546	63%
29-30	1,030,731	3.5%	56,566	0	4.00%	16,298		423,756	631,647	67%
30-31	1,066,806	3.5%	57,132	0	4.00%	10,266	224,237	266,917	478,168	56%
31-32	1,104,144	3.5%	57,703	0	4.00%	12,985		337,605	553,378	61%
32-33	1,142,789	3.5%	58,280	0	4.00%	14,832	25,095	385,621	607,433	63%
33-34	1,182,787	3.5%	58,863	0	4.00%	11,347	160,808	295,023	525,039	56%
34-35	1,224,185	3.5%	59,452	0	4.00%	13,700	11,972	356,203	596,005	60%
35-36	1,267,031	3.5%	60,046	0	4.00%	16,650		432,899	684,119	63%
36-37	1,311,377	3.5%	60,647	0	4.00%	19,742		513,287	777,672	66%
37-38	1,357,275	3.5%	61,253	0	4.00%	22,982		597,521	876,935	68%
38-39	1,404,780	3.5%	61,866	0	4.00%	23,048	83,180	599,255	896,102	67%
39-40	1,453,947	3.5%	62,484	0	4.00%	25,763	17,668	669,834	986,355	68%
40-41	1,504,835	3.5%	63,109	0	4.00%	29,318		762,261	1,100,755	69%
41-42	1,557,505	3.5%	63,740	0	4.00%	33,040		859,041	1,221,954	70%
42-43	1,612,017	3.5%	64,378	0	4.00%	22,753	354,602	591,570	983,276	60%
43-44	1,668,438	3.5%	65,021	0	4.00%	18,239	200,611	474,220	898,620	53%
44-45	1,726,833	3.5%	65,672	0	4.00%	20,918	16,937	543,872	1,004,203	54%
45-46	1,787,272	3.5%	66,328	0	4.00%	24,408		634,609	1,134,220	56%
46-47	1,849,827	3.5%	66,992	0	4.00%	27,165	22,479	706,287	1,248,841	57%
47-48	1,914,571	3.5%	67,661	0	4.00%	30,958		804,906	1,394,177	58%
48-49	1,981,581	3.5%	68,338	0	4.00%	12,227	567,581	317,890	960,710	33%
49-50	2,050,936	3.5%	69,021	0	4.00%	15,476	,	402,388	1,103,199	36%
50-51	2,122,719	3.5%	69,712	0	4.00%	18,054	20,759	469,394	1,233,001	38%
51-52	2,197,014	3.5%	70,409	0	4.00%	21,592	,	561,395	1,392,774	40%
52-53	2,273,910	3.5%	71,113	0	4.00%	25,300		657,808	1,562,221	42%
	, ,		- 7 -	-		- 7		,	, ,	





Chart illustrates year end balances and expenditures with the level of contributions necessary to maintain adequate funding.



This chart illustrates annual expenditures and compares the current funding plan to the recommended funding plan.

	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33
Beginning Balance		53,288	111,393	161,030	215,115	281,389	350,891	423,756	266,917	337,605
Annual Assessment	53,288	53,821	54,359	54,903	55,452	56,006	56,566	57,132	57,703	58,280
Interest Earned		4,284	6,193	8,274	10,823	13,496	16,298	10,266	12,985	14,832
Expenditures			10,915	9,091				224,237		25,095
Fully Funded Reserves	266,439	321,725	369,258	422,007	487,735	557,546	631,647	478,168	553,378	607,433
Percent Fully Funded	20%	35%	44%	51%	58%	63%	67%	56%	61%	63%
<b>Ending Balance</b>	53,288	111,393	161,030	215,115	281,389	350,891	423,756	266,917	337,605	385,621

Description

Misc. Site Components Pedestal Cluster Mailboxes

**Misc. Site Components Total:** 

Street/Lot Resurfacing

Asphalt Mill/Overlay - Amenity Lot

**Street/Lot Resurfacing Total:** 

Fencing & Gates

Aluminum Fence - Amenity

Chain Link Fence VC - Tennis/Basketball Courts

Wood/Wire Fence - Dog Park

Fencing & Gates Total:

Site Lighting

Decorative Light Poles - Amenity

Misc. Building Components

Refurbishment Allowance - Restrooms Windows/Ext. Door Allowance - Clubhouse

**Misc. Building Components Total:** 

Roofing

Standing Seam Metal Roof - Clubhouse

	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33
Description					3	_0 _/	_, _,	0001		
Exterior Painting										
Clubhouse				9,091						
Exterior Painting Total:				9,091						
Flooring										
Rubber Flooring - Fitness Room										11,208
Flooring Total:										11,208
Furniture Fixtures & Equipment										
Access Control System - Amenity										
Camera System Allowance										
Fitness Equipment Allowance										
Pool Furniture Allowance (full replacement)										
Furniture Fixtures & Equipment Total:										
HVAC										
Heat Pump - Fitness Room 3.5 Ton								7,125		
Heat Pump - Office/Restrooms 3.5 Ton Aaon Unit_								11,451		
HVAC Total:								18,575		
Swimming Pool										
Concrete Pavers - Pool Deck										
Pool Filtration Refurbishment Allowance										
Pool Lift										
Pool Resurfacing/Tile								167,493		
Retractable Shade Sails Shade Structure Frame/Fabric - Pool								38,168		
Swimming Pool Total:								205,661		
								205,001		
Tennis/Basketball Courts										
Asphalt Resurfacing (color coat)			10,915							13,887
Basketball Pole/Goal										
Tennis/Basketball Courts Total:			10,915							13,887

	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33
Description										
Playground										
Play Equipment Allowance										
Playground Total:										
Operating Expense										
Concrete Walk/Curb Repair	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Exhaust Fans	Unfunded									
Irrigation Repair	Unfunded									
Landscape Replacement	Unfunded									
Monument Sign Refurbishment	Unfunded									
Park Benches/Trash Cans	Unfunded									
Pool Furniture Allowance (partial replacement)	Unfunded									
Pool Play Equip. Refurbish Allowance	Unfunded									
Pool Pumps/Equip. Partial Replacement	Unfunded									
Shade Structure Fabric - Pool	Unfunded									
Water Coolers	Unfunded									
Components Not Included										
Building Foundation/Frame	Unfunded									
Concrete Pavers - Roundabout	Unfunded									
Lightning Protection System	Unfunded									
Stormwater Pond Dredging	Unfunded									
Stormwater Pond Pipe/Structures	Unfunded									
Stormwater System Evaluation	Unfunded									
Tennis/Basketball Court Replacement	Unfunded									
Year Total:			10,915	9,091				224,237		25,095

			2= 2 <	2 : 2 =	2= 20	•••	20.40	40.44		10.10
	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43
Beginning Balance	385,621	295,023	356,203	432,899	513,287	597,521	599,255	669,834	762,261	859,041
Annual Assessment	58,863	59,452	60,046	60,647	61,253	61,866	62,484	63,109	63,740	64,378
Interest Earned	11,347	13,700	16,650	19,742	22,982	23,048	25,763	29,318	33,040	22,753
Expenditures	160,808	11,972				83,180	17,668			354,602
<b>Fully Funded Reserves</b>	525,039	596,005	684,119	777,672	876,935	896,102	986,355	1,100,755	1,221,954	983,276
Percent Fully Funded	56%	60%	63%	66%	68%	67%	68%	69%	70%	60%
<b>Ending Balance</b>	295,023	356,203	432,899	513,287	597,521	599,255	669,834	762,261	859,041	591,570
Description										
Description Miss Site Components										
Misc. Site Components Pedestal Cluster Mailboxes										
Misc. Site Components Total:										
wisc. Site Components Total:										
Street/Lot Resurfacing										
Asphalt Mill/Overlay - Amenity Lot						46,778				
Street/Lot Resurfacing Total:						46,778				
Fencing & Gates										
Aluminum Fence - Amenity										
Chain Link Fence VC - Tennis/Basketball Courts										
Wood/Wire Fence - Dog Park						16,298				
Fencing & Gates Total:						16,298				
						-,				
Site Lighting										
Decorative Light Poles - Amenity										
Misc. Building Components										
Refurbishment Allowance - Restrooms										
Windows/Ext. Door Allowance - Clubhouse										

**Misc. Building Components Total:** 

Standing Seam Metal Roof - Clubhouse

Roofing

	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43
Description										
Exterior Painting										
Clubhouse		11,972								15,765
Exterior Painting Total:		11,972								15,765
Flooring										
Rubber Flooring - Fitness Room										
Flooring Total:										
Furniture Fixtures & Equipment										
Access Control System - Amenity	11,285									
Camera System Allowance	8,464									
Fitness Equipment Allowance	49,371									
Pool Furniture Allowance (full replacement)	35,265									
Furniture Fixtures & Equipment Total:	104,384									
HVAC										
Heat Pump - Fitness Room 3.5 Ton										10,766
Heat Pump - Office/Restrooms 3.5 Ton Aaon Unit										17,303
HVAC Total:										28,069
Swimming Pool										
Concrete Pavers - Pool Deck										
Pool Filtration Refurbishment Allowance										
Pool Lift						20,104				
Pool Resurfacing/Tile										253,093
Retractable Shade Sails										57,675
Shade Structure Frame/Fabric - Pool						••••				210 7 60
Swimming Pool Total:						20,104				310,768
Tennis/Basketball Courts										
Asphalt Resurfacing (color coat)							17,668			
Basketball Pole/Goal										
Tennis/Basketball Courts Total:							17,668			

	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43
Description										
Playground										
Play Equipment Allowance	56,424									
Playground Total:	56,424									
Operating Expense										
Concrete Walk/Curb Repair	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Exhaust Fans	Unfunded									
Irrigation Repair	Unfunded									
Landscape Replacement	Unfunded									
Monument Sign Refurbishment	Unfunded									
Park Benches/Trash Cans	Unfunded									
Pool Furniture Allowance (partial replacement)	Unfunded									
Pool Play Equip. Refurbish Allowance	Unfunded									
Pool Pumps/Equip. Partial Replacement	Unfunded									
Shade Structure Fabric - Pool	Unfunded									
Water Coolers	Unfunded									
Components Not Included										
Building Foundation/Frame	Unfunded									
Concrete Pavers - Roundabout	Unfunded									
Lightning Protection System	Unfunded									
Stormwater Pond Dredging	Unfunded									
Stormwater Pond Pipe/Structures	Unfunded									
Stormwater System Evaluation	Unfunded									
Tennis/Basketball Court Replacement	Unfunded									
Year Total:	160,808	11,972				83,180	17,668			354,602

	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53
Beginning Balance Annual Assessment	591,570 65,021	474,220 65,672	543,872 66,328	634,609 66,992	706,287 67,661	804,906 68,338	317,890 69,021	402,388 69,712	469,394 70,409	561,395 71,113
Interest Earned	18,239	20,918	24,408	27,165	30,958	12,227	15,476	18,054	21,592	25,300
Expenditures	200,611	16,937		22,479		567,581		20,759		
Fully Funded Reserves	898,620	1,004,203	1,134,220	1,248,841	1,394,177	960,710	1,103,199	1,233,001	1,392,774	1,562,221
Percent Fully Funded Ending Balance	53% 474,220	54% 543,872	56% 634,609	57% 706,287	58% 804,906	33% 317,890	36% 402,388	38% 469,394	40% 561,395	42% 657,808
Ending Dalance	474,220	343,012	034,009	700,287	004,900	317,690	402,366	409,394	301,393	037,000
Description										
Misc. Site Components										
Pedestal Cluster Mailboxes						221,200				
Misc. Site Components Total:						221,200				
Street/Lot Resurfacing										
Asphalt Mill/Overlay - Amenity Lot										
Street/Lot Resurfacing Total:										
Fencing & Gates										
Aluminum Fence - Amenity	35,601									
Chain Link Fence VC - Tennis/Basketball Courts	29,290									
Wood/Wire Fence - Dog Park										
Fencing & Gates Total:	64,891									
Site Lighting										
Decorative Light Poles - Amenity										
Misc. Building Components										
Refurbishment Allowance - Restrooms	90,352									
Windows/Ext. Door Allowance - Clubhouse  Misc. Building Components Total:	90,352									
-	70,002									
Roofing										
Standing Seam Metal Roof - Clubhouse										

	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53
Description										
Exterior Painting										
Clubhouse								20,759		
Exterior Painting Total:								20,759		
Flooring										
Rubber Flooring - Fitness Room		16,937								
Flooring Total:		16,937								
Furniture Fixtures & Equipment										
Access Control System - Amenity						18,906				
Camera System Allowance						14,179				
Fitness Equipment Allowance						82,714				
Pool Furniture Allowance (full replacement)						59,081				
Furniture Fixtures & Equipment Total:						174,880				
HVAC										
Heat Pump - Fitness Room 3.5 Ton										
Heat Pump - Office/Restrooms 3.5 Ton Aaon Unit										
HVAC Total:										
Swimming Pool										
Concrete Pavers - Pool Deck										
Pool Filtration Refurbishment Allowance						76,971				
Pool Lift										
Pool Resurfacing/Tile										
Retractable Shade Sails										
Shade Structure Frame/Fabric - Pool	31,837									
Swimming Pool Total:	31,837					76,971				
Tennis/Basketball Courts										
Asphalt Resurfacing (color coat)				22,479						
Basketball Pole/Goal	13,531									
Tennis/Basketball Courts Total:	13,531			22,479						

	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53
Description										
Playground										
Play Equipment Allowance						94,530				
Playground Total:						94,530				
Operating Expense										
Concrete Walk/Curb Repair	Unfunded									
Dumpster Enclosure/Gates	Unfunded									
Exhaust Fans	Unfunded									
Irrigation Repair	Unfunded									
Landscape Replacement	Unfunded									
Monument Sign Refurbishment	Unfunded									
Park Benches/Trash Cans	Unfunded									
Pool Furniture Allowance (partial replacement)	Unfunded									
Pool Play Equip. Refurbish Allowance	Unfunded									
Pool Pumps/Equip. Partial Replacement	Unfunded									
Shade Structure Fabric - Pool	Unfunded									
Water Coolers	Unfunded									
Components Not Included										
Building Foundation/Frame	Unfunded									
Concrete Pavers - Roundabout	Unfunded									
Lightning Protection System	Unfunded									
Stormwater Pond Dredging	Unfunded									
Stormwater Pond Pipe/Structures	Unfunded									
Stormwater System Evaluation	Unfunded									
Tennis/Basketball Court Replacement	Unfunded									
Year Total:	200,611	16,937		22,479		567,581		20,759		


Description	Expenditures
No Replacement in 23-24	
No Replacement in 24-25	
Replacement Year 25-26	
Tennis/Basketball Courts	
Asphalt Resurfacing (color coat)	10,915
Total for 2025 - 2026	\$10,915
Replacement Year 26-27	
Exterior Painting	
Clubhouse	9,091
Total for 2026 - 2027	\$9,091
No Replacement in 27-28	
No Replacement in 28-29	
No Replacement in 29-30	
Replacement Year 30-31	
HVAC	
Heat Pump - Fitness Room 3.5 Ton	7,125
Heat Pump - Office/Restrooms 3.5 Ton Aaon Unit	11,451
Swimming Pool	
Pool Resurfacing/Tile	167,493
Retractable Shade Sails	38,168
Total for 2030 - 2031	\$224,237
No Replacement in 31-32	
Replacement Year 32-33	
Flooring	
Rubber Flooring - Fitness Room	11,208
Tennis/Basketball Courts	
Asphalt Resurfacing (color coat)	13,887
Total for 2032 - 2033	\$25,095

Description	Expenditures
Replacement Year 33-34	
Furniture Fixtures & Equipment	
Access Control System - Amenity	11,285
Camera System Allowance	8,464
Fitness Equipment Allowance	49,371
Pool Furniture Allowance (full replacement)	35,265
Playground	
Play Equipment Allowance	56,424
Total for 2033 - 2034	<b>\$160,808</b>
Replacement Year 34-35	
Exterior Painting	
Clubhouse	11,972
Total for 2034 - 2035	<b>\$11,972</b>
No Replacement in 35-36	
No Replacement in 36-37	
No Replacement in 37-38	
Replacement Year 38-39	
Street/Lot Resurfacing	
Asphalt Mill/Overlay - Amenity Lot	46,778
Fencing & Gates	
Wood/Wire Fence - Dog Park	16,298
Swimming Pool	
Pool Lift	20,104
Total for 2038 - 2039	\$83,180
Replacement Year 39-40	
Tennis/Basketball Courts	
Asphalt Resurfacing (color coat)	17,668
Total for 2039 - 2040	<b>\$17,668</b>
10tai 101 2037 - 2040	φ17,000

No Replacement in 40-41

Description	Expenditures
No Replacement in 41-42	
Replacement Year 42-43	
Exterior Painting Clubhouse	15 765
HVAC	15,765
Heat Pump - Fitness Room 3.5 Ton	10,766
Heat Pump - Office/Restrooms 3.5 Ton Aaon Unit	17,303
Swimming Pool	
Pool Resurfacing/Tile	253,093
Retractable Shade Sails	57,675
Total for 2042 - 2043	\$354,602
Replacement Year 43-44	
Fencing & Gates	
Aluminum Fence - Amenity	35,601
Chain Link Fence VC - Tennis/Basketball Courts	29,290
Misc. Building Components Refurbishment Allowance - Restrooms	90,352
Swimming Pool	
Shade Structure Frame/Fabric - Pool	31,837
Tennis/Basketball Courts	
Basketball Pole/Goal	13,531
Total for 2043 - 2044	\$200,611
Replacement Year 44-45	
Flooring	
Rubber Flooring - Fitness Room	16,937
Total for 2044 - 2045	\$16,937
No Replacement in 45-46	
Replacement Year 46-47	
Tennis/Basketball Courts	
Asphalt Resurfacing (color coat)	22,479
Total for 2046 - 2047	<b>\$22,479</b>

Description	Expenditures
No Replacement in 47-48	
Replacement Year 48-49	
Misc. Site Components	
Pedestal Cluster Mailboxes	221,200
Furniture Fixtures & Equipment	
Access Control System - Amenity	18,906
Camera System Allowance	14,179
Fitness Equipment Allowance	82,714
Pool Furniture Allowance (full replacement)	59,081
Swimming Pool	
Pool Filtration Refurbishment Allowance	76,971
Playground	
Play Equipment Allowance	94,530
Total for 2048 - 2049	<del>\$567,581</del>
No Replacement in 49-50	
Replacement Year 50-51	
Exterior Painting	
Clubhouse	20,759
Total for 2050 - 2051	\$20,759
No Replacement in 51-52	
No Replacement in 52-53	



	<b>~</b> 9)	A CONTRACTION OF THE PARTY OF T	<b>&gt;</b>		aeat.	idisto		*
Description	्द : पु <sup>क्</sup> ट्ड <sup>म्</sup> ट	€6/36.gg	Setu	<b>Vill</b> ight N	Qenii	Signs .	ع المالية الما	CHI CO
Misc. Site Components  Pedestal Cluster Mailboxes  Misc. Site Components - Total	2019	48-49	30	0	25	36 Each	2,600.00	93,600 \$93,600
Street/Lot Resurfacing Asphalt Mill/Overlay - Amenity Lot Street/Lot Resurfacing - Total	2019	38-39	20	0	15	1,662 Square Yards	16.80	27,922 \$27,922
Fencing & Gates Aluminum Fence - Amenity Chain Link Fence VC - Tennis/Basketball C Wood/Wire Fence - Dog Park Fencing & Gates - Total	2019 2019 2019	43-44 43-44 38-39	25 25 20	0 0 0	20 20 15	426 Linear Feet 460 Linear Feet 304 Linear Feet	42.00 32.00 32.00	17,892 14,720 <u>9,728</u> \$42,340
Site Lighting Decorative Light Poles - Amenity Site Lighting - Total	2019	53-54	35	0	30	14 Each	2,800.00	39,200 \$39,200
Misc. Building Components Refurbishment Allowance - Restrooms Windows/Ext. Door Allowance - Clubhouse Misc. Building Components - Total	2019 2019	43-44 58-59	25 40	0	20 35	528 Lump Sum 1 Lump Sum	86.00 48,000.00	45,408 <u>48,000</u> \$93,408
Roofing Standing Seam Metal Roof - Clubhouse Roofing - Total	2019	53-54	35	0	30	6,200 Square Feet	12.80	79,360 \$79,360
Exterior Painting Clubhouse Exterior Painting - Total	2019	26-27	8	0	3	1 Lump Sum	8,200.00	<u>8,200</u> \$8,200
Flooring Rubber Flooring - Fitness Room Flooring - Total	2019	32-33	12	2	9	1,028 Square Feet	8.00	<u>8,224</u> \$8,224
Furniture Fixtures & Equipment Access Control System - Amenity Camera System Allowance Fitness Equipment Allowance Pool Furniture Allowance (full replacement) Furniture Fixtures & Equipment - Total	2019 2019 2019 2019	33-34 33-34 33-34 33-34	15 15 15 15	0 0 0 0	10 10 10 10	1 Lump Sum 1 Lump Sum 1 Lump Sum 1 Lump Sum	8,000.00 6,000.00 35,000.00 25,000.00	8,000 6,000 35,000 <u>25,000</u> \$74,000

		2 Days	<u>*</u>		eji	.5 <sup>60</sup>		
Description	On 25.16.		ر چارا	· . is	Polar Colar	Silis Silis	المُلِّ المُلْكِ	Chi Co
Description	25	Æ 7	$\sim$	\$	Æ.	<b>₩</b>	\$ 0	0.0
HVAC								
Heat Pump - Fitness Room 3.5 Ton	2019	30-31	12	0	7	1 Each	5,600.00	5,600
Heat Pump - Office/Restrooms 3.5 Ton Aao HVAC - Total	2019	30-31	12	0	7	1 Each	9,000.00	<u>9,000</u> \$14,600
Swimming Pool								
Concrete Pavers - Pool Deck	2019	53-54	35	0	30	9,338 Square Feet	8.40	78,439
Pool Filtration Refurbishment Allowance	2019	48-49	30	0	25	3,257 Surface Feet	10.00	32,570
Pool Lift	2019	38-39	20	0	15	1 Each	12,000.00	12,000
Pool Resurfacing/Tile	2019	30-31	12	0	7	4,114 Square Feet	32.00	131,648
Retractable Shade Sails Shade Structure Frame/Fabric - Pool	2019 2019	30-31 43-44	12 25	0	7 20	5 Each 2 Each	6,000.00	30,000
Swimming Pool - Total	2019	43-44	23	U	20	2 Each	8,000.00	16,000 \$300,657
Tennis/Basketball Courts								
Asphalt Resurfacing (color coat)	2019	25-26	7	0	2	1,213 Square Yards	8.40	10,189
Basketball Pole/Goal	2019	43-44	25	0	20	1 Lump Sum	6,800.00	6,800
Tennis/Basketball Courts - Total						-		\$16,989
Playground								
Play Equipment Allowance Playground - Total	2019	33-34	15	0	10	1 Lump Sum	40,000.00	40,000 \$40,000
Onesting Ermonge								
Operating Expense Concrete Walk/Curb Repair	1)	nfunded						
Dumpster Enclosure/Gates		nfunded Infunded						
Exhaust Fans		nfunded nfunded						
Irrigation Repair		nfunded						
Landscape Replacement	U	nfunded						
Monument Sign Refurbishment		nfunded						
Park Benches/Trash Cans		nfunded						
Pool Furniture Allowance (partial replacem		nfunded						
Pool Play Equip. Refurbish Allowance Pool Pumps/Equip. Partial Replacement		nfunded Infunded						
Shade Structure Fabric - Pool		njunaea Infunded						
Water Coolers		nfunded nfunded						
Operating Expense - Total		<b>y</b>						
<b>Components Not Included</b>								
Building Foundation/Frame		nfunded						
Concrete Pavers - Roundabout		nfunded						
Lightning Protection System		nfunded						
Stormwater Pond Dredging		nfunded						
Stormwater Pond Pipe/Structures Stormwater System Evaluation		nfunded Infunded						
Stormwater System Evaluation	U	пјинава						

gë gjetë

Description

Components Not Included continued...
Tennis/Basketball Court Replacement
Components Not Included - Total

Unfunded

Total Asset Summary \$838,500

Misc. Site Components 1003 Pedestal Cluster Mailboxes 48-49 5-6  Street/Lot Resurfacing 1005 Asphalt Mill/Overlay - Amenity Lot 38-39 5-7  Fencing & Gates 1019 Aluminum Fence - Amenity 43-44 5-8 1022 Chain Link Fence VC - Tennis/Basketball Courts 43-44 5-8 1031 Wood/Wire Fence - Dog Park 38-39 5-9  Site Lighting 1002 Decorative Light Poles - Amenity 53-54 5-10  Misc. Building Components 1013 Refurbishment Allowance - Restrooms 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
1003 Pedestal Cluster Mailboxes       48-49       5-6         Street/Lot Resurfacing         1005 Asphalt Mill/Overlay - Amenity Lot       38-39       5-7         Fencing & Gates         1019 Aluminum Fence - Amenity       43-44       5-8         1022 Chain Link Fence VC - Tennis/Basketball Courts       43-44       5-8         1031 Wood/Wire Fence - Dog Park       38-39       5-9         Site Lighting         1002 Decorative Light Poles - Amenity       53-54       5-10         Misc. Building Components         1013 Refurbishment Allowance - Restrooms       43-44       5-11         1007 Windows/Ext. Door Allowance - Clubhouse       58-59       5-11         Roofing         1004 Standing Seam Metal Roof - Clubhouse       53-54       5-12         Exterior Painting         1006 Clubhouse       26-27       5-13         Flooring         1009 Rubber Flooring - Fitness Room       32-33       5-14         Furniture Fixtures & Equipment					
Tools Asphalt Mill/Overlay - Amenity Lot         38-39         5-7           Fencing & Gates           1019         Aluminum Fence - Amenity         43-44         5-8           1022         Chain Link Fence VC - Tennis/Basketball Courts         43-44         5-8           1031         Wood/Wire Fence - Dog Park         38-39         5-9           Site Lighting           1002         Decorative Light Poles - Amenity         53-54         5-10           Misc. Building Components           1013         Refurbishment Allowance - Restrooms         43-44         5-11           1007         Windows/Ext. Door Allowance - Clubhouse         58-59         5-11           Roofing           1004         Standing Seam Metal Roof - Clubhouse         53-54         5-12           Exterior Painting           1006         Clubhouse         26-27         5-13           Flooring           1009         Rubber Flooring - Fitness Room         32-33         5-14           Furniture Fixtures & Equipment					
Tools Asphalt Mill/Overlay - Amenity Lot         38-39         5-7           Fencing & Gates           1019         Aluminum Fence - Amenity         43-44         5-8           1022         Chain Link Fence VC - Tennis/Basketball Courts         43-44         5-8           1031         Wood/Wire Fence - Dog Park         38-39         5-9           Site Lighting           1002         Decorative Light Poles - Amenity         53-54         5-10           Misc. Building Components           1013         Refurbishment Allowance - Restrooms         43-44         5-11           1007         Windows/Ext. Door Allowance - Clubhouse         58-59         5-11           Roofing           1004         Standing Seam Metal Roof - Clubhouse         53-54         5-12           Exterior Painting           1006         Clubhouse         26-27         5-13           Flooring           1009         Rubber Flooring - Fitness Room         32-33         5-14           Furniture Fixtures & Equipment					
Fencing & Gates           1019         Aluminum Fence - Amenity         43-44         5-8           1022         Chain Link Fence VC - Tennis/Basketball Courts         43-44         5-8           1031         Wood/Wire Fence - Dog Park         38-39         5-9           Site Lighting           1002         Decorative Light Poles - Amenity         53-54         5-10           Misc. Building Components           1013         Refurbishment Allowance - Restrooms         43-44         5-11           1007         Windows/Ext. Door Allowance - Clubhouse         58-59         5-11           Roofing           1004         Standing Seam Metal Roof - Clubhouse         53-54         5-12           Exterior Painting           1006         Clubhouse         26-27         5-13           Flooring           1009         Rubber Flooring - Fitness Room         32-33         5-14           Furniture Fixtures & Equipment					
1019 Aluminum Fence - Amenity 1022 Chain Link Fence VC - Tennis/Basketball Courts 1031 Wood/Wire Fence - Dog Park 1031 Wood/Wire Fence - Dog Park 1031 Wood/Wire Fence - Dog Park 1002 Decorative Light Poles - Amenity 1002 Decorative Light Poles - Amenity 1013 Refurbishment Allowance - Restrooms 1014 Refurbishment Allowance - Clubhouse 1004 Standing Seam Metal Roof - Clubhouse 1005 Clubhouse 1006 Clubhouse 1006 Clubhouse 1007 Rubber Flooring - Fitness Room 1009 Rubber Flooring - Fitness Room 1009 Rubber Flooring - Fitness Room 1009 Seam Metal Roof - Clubhouse 1009 Rubber Flooring - Fitness Room					
1022 Chain Link Fence VC - Tennis/Basketball Courts 43-44 5-8 1031 Wood/Wire Fence - Dog Park 38-39 5-9  Site Lighting 1002 Decorative Light Poles - Amenity 53-54 5-10  Misc. Building Components 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Site Lighting 1002 Decorative Light Poles - Amenity  Misc. Building Components 1013 Refurbishment Allowance - Restrooms 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Site Lighting 1002 Decorative Light Poles - Amenity 53-54 5-10  Misc. Building Components 1013 Refurbishment Allowance - Restrooms 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Misc. Building Components  1013 Refurbishment Allowance - Restrooms 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Misc. Building Components  1013 Refurbishment Allowance - Restrooms 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Misc. Building Components  1013 Refurbishment Allowance - Restrooms 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
1013 Refurbishment Allowance - Restrooms 43-44 5-11 1007 Windows/Ext. Door Allowance - Clubhouse 58-59 5-11  Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Roofing 1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
1004 Standing Seam Metal Roof - Clubhouse 53-54 5-12  Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Exterior Painting 1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
1006 Clubhouse 26-27 5-13  Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
Flooring 1009 Rubber Flooring - Fitness Room 32-33 5-14  Furniture Fixtures & Equipment					
1009 Rubber Flooring - Fitness Room 32-33 5-14 <b>Furniture Fixtures &amp; Equipment</b>					
1009 Rubber Flooring - Fitness Room 32-33 5-14 <b>Furniture Fixtures &amp; Equipment</b>					
Furniture Fixtures & Equipment					
<u> </u>					
1032 Access Control System - Amenity 33-34 5-15					
1018 Camera System Allowance 33-34 5-15					
1008 Fitness Equipment Allowance 33-34 5-15					
1015 Pool Furniture Allowance (full replacement) 33-34 5-16					
HVAC					
1011 Heat Pump - Fitness Room 3.5 Ton 30-31 5-17					
1012 Heat Pump - Office/Restrooms 3.5 Ton Aaon Unit 30-31 5-17					
1012 Heat I timp - Office/Restrooms 3.3 Ton Adon Offic 30-31 3-1/					
Swimming Pool					
1014 Concrete Pavers - Pool Deck 53-54 5-18					

Asset I	DDescription	Replacement	Page
Swimm	ing Pool Continued		
1030	Pool Filtration Refurbishment Allowance	48-49	5-18
1028	Pool Lift	38-39	5-19
1001	Pool Resurfacing/Tile	30-31	5-19
1027	Retractable Shade Sails	30-31	5-20
1025	Shade Structure Frame/Fabric - Pool	43-44	5-20
Tennis	/Basketball Courts		
1023	Asphalt Resurfacing (color coat)	25-26	5-21
1038	Basketball Pole/Goal	43-44	5-21
Playgr	ound		
1020	Play Equipment Allowance	33-34	5-22
Onergi	ting Expense		
1037	Concrete Walk/Curb Repair	23-24	5-23
1033	Dumpster Enclosure/Gates	23-24	5-23
1058	Exhaust Fans	23-24	5-24
1054	Irrigation Repair	23-24	5-24
1053	Landscape Replacement	23-24	5-24
1034	Monument Sign Refurbishment	23-24	5-24
1021	Park Benches/Trash Cans	23-24	5-25
1016	Pool Furniture Allowance (partial replacement)	23-24	5-25
1017	Pool Play Equip. Refurbish Allowance	23-24	5-26
1029	Pool Pumps/Equip. Partial Replacement	23-24	5-26
1026	Shade Structure Fabric - Pool	23-24	5-27
1010	Water Coolers	23-24	5-27
Compo	onents Not Included		
1057	Building Foundation/Frame	23-24	5-29
1039	Concrete Pavers - Roundabout	23-24	5-29
1059	Lightning Protection System	23-24	5-29
1051	Stormwater Pond Dredging	23-24	5-29
1052	Stormwater Pond Pipe/Structures	23-24	5-30
1050	Stormwater System Evaluation	23-24	5-30
1024	Tennis/Basketball Court Replacement	23-24	5-30
	Total Funded Assets	26	
	Total Unfunded Assets	<u>19</u>	
	Total Assets	45	

## Pedestal Cluster Mailboxes - 2048

 uster Mailboxes - 2048
 36 Each
 @ \$2,600.00

 Asset ID
 1003
 Asset Actual Cost
 \$93,600.00

 Percent Replacement
 100%

 Category Misc. Site Components
 Future Cost
 \$221,199.73

Placed in Service August 2019
Useful Life 30
Replacement Year 48-49
Remaining Life 25



## Asphalt Mill/Overlay - Amenity Lot - 2038

Asset ID	1005	1,662 Square Yards Asset Actual Cost Percent Replacement	@ \$16.80 \$27,921.60 100%
Category	Street/Lot Resurfacing	Future Cost	\$46,778.42
Placed in Service	August 2019		
Useful Life	20		
Replacement Year	38-39		
Remaining Life	15		



### Aluminum Fence - Amenity - 2043

Asset ID 1019

 426 Linear Feet
 @ \$42.00

 Asset Actual Cost
 \$17,892.00

 Percent Replacement
 100%

 Future Cost
 \$35,601.30

Category Fencing & Gates
Placed in Service August 2019
Useful Life 25
Replacement Year 43-44
Remaining Life 20



#### Chain Link Fence VC - Tennis/Basketball Courts - 2043

Asset ID 1022

460 Linear Feet @ \$32.00 Asset Actual Cost \$14,720.00 Percent Replacement 100% Future Cost \$29,289.69

Category Fencing & Gates
Placed in Service August 2019
Useful Life 25
Replacement Year 43-44
Remaining Life 20





# Wood/Wire Fence - Dog Park - 2038

Asset ID	1031	304 Linear Feet Asset Actual Cost Percent Replacement	@ \$32.00 \$9,728.00 100%
Category	Fencing & Gates	Future Cost	\$16,297.79
Placed in Service	August 2019		
Useful Life	20		
Replacement Year	38-39		
Remaining Life	15		



Decorative Light Poles	- Amenity - 2053	14 Each	@ \$2,800.00
Asset ID	1002	Asset Actual Cost	\$39,200.00
		Percent Replacement	100%
Category	Site Lighting	Future Cost	\$110,026.31
Placed in Service	August 2019		
Useful Life	35		
Replacement Year	53-54		
Remaining Life	30		



#### Refurbishment Allowance - Restrooms - 2043

Asset ID 1013 Asset Actual Cost \$45,408.00
Percent Replacement 100%
Categorisc. Building Components Future Cost \$90,352.33

Placed in Service August 2019
Useful Life 25
Replacement Year 43-44
Remaining Life 20





#### Windows/Ext. Door Allowance - Clubhouse - 2058

Asset ID 1007 Asset Actual Cost \$48,000.00
Percent Replacement 100%
Categorisc. Building Components Future Cost \$160,012.34

Placed in Service August 2019
Useful Life 40
Replacement Year 58-59
Remaining Life 35



# Standing Seam Metal Roof - Clubhouse - 2053

		6,200 Square Feet	@ \$12.80
Asset ID	1004	Asset Actual Cost	\$79,360.00
		Percent Replacement	100%
Category	Roofing	Future Cost	\$222,747.15
Placed in Service	August 2019		
Useful Life	35		
Replacement Year	53-54		
Remaining Life	30		



## Clubhouse - 2026

Remaining Life

Asset Actual Cost \$8,200.00 Asset ID 1006 Percent Replacement 100% **Exterior Painting** Future Cost \$9,091.49 Category Placed in Service August 2019 8 Useful Life Replacement Year 26-27

3





1 Lump Sum

@ \$8,200.00

# Rubber Flooring - Fitness Room - 2032

Asset ID	1009	1,028 Square Feet Asset Actual Cost Percent Replacement	@ \$8.00 \$8,224.00 100%
Category	Flooring	Future Cost	\$11,208.47
Placed in Service	August 2019		
Useful Life	12		
Adjustment	2		
Replacement Year	32-33		
Remaining Life	9		



# Access Control System - Amenity - 2033

Asset ID	1032	1 Lump Sum Asset Actual Cost	@ \$8,000.00 \$8,000.00
		Percent Replacement	100%
<b>Gatengioury</b> e Fixtu	res & Equipment	Future Cost	\$11,284.79
Placed in Service	August 2019		
Useful Life	15		
Replacement Year	33-34		
Remaining Life	10		



#### Camera System Allowance - 2033

mera System Allowanco	e - 2033	1 Lump Sum	@ \$6,000.00
Asset ID	1018	Asset Actual Cost	\$6,000.00
		Percent Replacement	100%
<b>Gatergioury</b> e Fixtur	es & Equipment	Future Cost	\$8,463.59
Placed in Service	August 2019		
Useful Life	15		
Replacement Year	33-34		
Remaining Life	10		

# Fitness Equipment Allowance - 2033

		1 Lump Sum	@ \$35,000.00
Asset ID	1008	Asset Actual Cost	\$35,000.00
		Percent Replacement	100%
Catengiourye Fi	xtures & Equipment	Future Cost	\$49,370.96
Placed in Service	August 2019		
Useful Life	15		
Replacement Year	33-34		
Remaining Life	10		

Fitness Equipment Allowance continued...



## Pool Furniture Allowance (full replacement) - 2033

Placed in Service
Useful Life
August 2019
Useful Life
Replacement Year
Remaining Life
August 2019
15
15
10





# Heat Pump - Fitness Room 3.5 Ton - 2030

		1 Each	@ \$5,600.00
Asset ID	1011	Asset Actual Cost	\$5,600.00
		Percent Replacement	100%
Category	HVAC	Future Cost	\$7,124.76
Placed in Service	August 2019		
Useful Life	12		
Replacement Year	30-31		
Remaining Life	7		



# Heat Pump - Office/Restrooms 3.5 Ton Aaon Unit - 2030

		1 Each	@ \$9,000.00
Asset ID	1012	Asset Actual Cost	\$9,000.00
		Percent Replacement	100%
Category	HVAC	Future Cost	\$11,450.51
Placed in Service	August 2019		
Useful Life	12		
Replacement Year	30-31		
Remaining Life	7		

## Concrete Pavers - Pool Deck - 2053

		9,338 Square Feet	@ \$8.40
Asset ID	1014	Asset Actual Cost	\$78,439.20
		Percent Replacement	100%
Category	Swimming Pool	Future Cost	\$220,162.65
Placed in Service	August 2019		

Useful Life 35
Replacement Year 53-54
Remaining Life 30





## Pool Filtration Refurbishment Allowance - 2048

		3,257 Surface Feet	@ \$10.00
Asset ID	1030	Asset Actual Cost	\$32,570.00
		Percent Replacement	100%
Category	Swimming Pool	Future Cost	\$76,970.89
Placed in Service	August 2019		
Useful Life	30		
Replacement Year	48-49		

25



Remaining Life



## Pool Lift - 2038

Asset ID 1028 Asset Actual Cost \$12,000.00

Percent Replacement 100%

Category Swimming Pool Future Cost \$20,104.19

Placed in Service
Useful Life
August 2019
Useful Life
Replacement Year
Remaining Life
August 2019
20
38-39



## Pool Resurfacing/Tile - 2030

Asset ID 1001 Asset Actual Cost \$131,648.00

Percent Replacement 1009

Category
Placed in Service
Useful Life
Replacement Year
Remaining Life
Swimming Pool
August 2019
30-31
7



#### Retractable Shade Sails - 2030

Asset ID 1027 Asset Actual Cost \$30,000.00

Percent Replacement 100%

Category Swimming Pool Future Cost \$38,168.38

Placed in Service August 2019
Useful Life 12
Replacement Year 30-31
Remaining Life 7



#### Shade Structure Frame/Fabric - Pool - 2043

2 Each @ \$8,000.00
Asset ID 1025 Asset Actual Cost \$16,000.00
Percent Replacement 100%
Category Swimming Pool Future Cost \$31,836.62

Placed in Service August 2019
Useful Life 25
Replacement Year 43-44
Remaining Life 20



## Asphalt Resurfacing (color coat) - 2025

Asset ID 1023

Categor Jennis/Basketball Courts
Placed in Service August 2019
Useful Life 7
Replacement Year 25-26
Remaining Life 2

1,213 Square Yards@ \$8.40Asset Actual Cost\$10,189.20Percent Replacement100%Future Cost\$10,914.93





#### Basketball Pole/Goal - 2043

Asset ID 1038

Categor Jennis/Basketball Courts
Placed in Service August 2019
Useful Life 25
Replacement Year 43-44
Remaining Life 20



# Play Equipment Allowance - 2033

@ \$40,000.00 1 Lump Sum Asset ID 1020 Asset Actual Cost \$40,000.00 Percent Replacement 100% Playground Future Cost \$56,423.95 Category

Placed in Service August 2019 15 Useful Life 33-34 Replacement Year Remaining Life 10





## Concrete Walk/Curb Repair

Asset ID 1037

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense October 2019

## Dumpster Enclosure/Gates

Asset ID 1033

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense October 2019



			Exhaust Fans
1000/	Asset Actual Cost	1058	Asset ID
100%	Percent Replacement Future Cost	Operating Expense	Catagory
	Tutule Cost	October 2019	Category Placed in Service
		0000001 2019	No Useful Life
			Irrigation Repair
	Asset Actual Cost	1054	Asset ID
100%	Percent Replacement		_
	Future Cost	Operating Expense	Category Placed in Service
		August 2019	No Useful Life
			140 Oscial Elic
		ent	Landscape Replacem
	Asset Actual Cost	1053	Asset ID
100%	Percent Replacement		
	Future Cost	Operating Expense	Category
		August 2019	Placed in Service
			No Useful Life
		rbishment	Monument Sign Refu
	Asset Actual Cost	1034	Asset ID
100%	Percent Replacement		
	Future Cost	Operating Expense	Category
		August 2019	Placed in Service

No Useful Life

Monument Sign Refurbishment continued...



## Park Benches/Trash Cans

Placed in Service No Useful Life

Category

Asset ID 1021

Operating Expense August 2019 Asset Actual Cost Percent Replacement Future Cost

100%



## Pool Furniture Allowance (partial replacement)

Asset ID 1016 Asset Actual Cost

Category Operating Expense
Placed in Service August 2019
No Useful Life

Percent Replacement Future Cost 100%

Pool Furniture Allowance (partial replacement) continued...





## Pool Play Equip. Refurbish Allowance

Asset ID

1017

Category Placed in Service No Useful Life Operating Expense August 2019 Asset Actual Cost Percent Replacement Future Cost

100%



## Pool Pumps/Equip. Partial Replacement

Asset ID 1029

Category Placed in Service No Useful Life Operating Expense August 2019 Asset Actual Cost Percent Replacement Future Cost

100%

Pool Pumps/Equip. Partial Replacement continued...





## Shade Structure Fabric - Pool

Asset ID 1026

Category Placed in Service No Useful Life Operating Expense August 2019 Asset Actual Cost Percent Replacement Future Cost

100%



## Water Coolers

Asset ID 1010

Category
Placed in Service
No Useful Life

Operating Expense August 2019 Asset Actual Cost Percent Replacement Future Cost

100%

Water Coolers continued...





Building Foundation/Frame

Asset ID 1057 Asset Actual Cost

100%

100%

Categorymponents Not Included Future Cost
Placed in Service August 2019

No Useful Life

Concrete Pavers - Roundabout

Asset ID 1039 Asset Actual Cost

Percent Replacement 100%
Categorymponents Not Included Future Cost

Categorymponents Not Included Placed in Service August 2019

No Useful Life

**Lightning Protection System** 

Asset ID 1059 Asset Actual Cost

Categorymponents Not Included Future Cost

Placed in Service August 2019 No Useful Life

Stormwater Pond Dredging

Asset ID 1051 Asset Actual Cost

Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service August 2019
No Useful Life

## Stormwater Pond Pipe/Structures

Asset ID 1052 Asset Actual Cost Percent Replacement

Categorymponents Not Included Future Cost
Placed in Service August 2019

Lan

## **Stormwater System Evaluation**

No Useful Life

Asset ID 1050 Asset Actual Cost

100%

Percent Replacement 100%
Categorymponents Not Included Future Cost
Placed in Service August 2019
No Useful Life

## Tennis/Basketball Court Replacement

Asset ID 1024 Asset Actual Cost
Percent Replacement 100%

**Future Cost** 

Categorymponents Not Included Placed in Service August 2019 No Useful Life



# **Report Navigation**

- **Executive Summary** provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
  - Level of Service is the type of reserve study
  - Funding Method is either Component Funding or Pooled Cash
  - Component Funding Contribution is a year one only amount
  - Current Funding Plan currently used by the Association
  - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
  - Year begins with your study year generally for a 30-year term
  - Current cost is the current replacement of all components
  - Annual contribution is the amount placed in reserves each year
  - Annual interest earned on your funds
  - Annual expenditures are the projected component replacement cost by year
  - Projected ending balance is the year end reserve fund balance
  - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
  - Percent Funded is a measure of fund strength
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- Cash Flow is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- **Annual Expenditure Detail** provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment (if included) is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- Component Detail Index allows quick access to the detail we have included for each component separated into categories
- Component Detail provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

#### **METHODOLOGY**

Reserve Analysis is a process that identifies capital expenses the District can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. <u>Baseline Funding</u> maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk; using this method requires regular analysis updates.

#### **CREDENTIALS**

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service attention to detail, quick response and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

#### TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

#### **DEFINITIONS**

**Adjustment to Useful Life:** Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

**Cash Flow Method:** A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

**Component Method:** A funding method that fully funds each reserve component then sums those for the annual contribution.

**Current Funding Plan:** The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

**Effective Age:** Difference of useful and remaining useful life.

**Fully Funded Balance:** Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

**Interest Contribution:** The interest that should be earned on invested reserves.

**Percent Funded:** Ratio of reserve balance to fully funded balance.

**Remaining Life:** Number of years a component is projected to continue to function.

**Threshold Funding:** This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

**Useful Life:** The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.